



WARDRAY GLASS CLEANER - GC100

We are a leading distributor for Corning Med-X® and Med-PET® glass for all types of radiation shielding involving X-ray and Gamma based PET radiation sources.

Cleaning and maintenance of lead glass

Do not use harsh abrasive cleaning chemicals or cleaning materials as these could damage the surface and leave scratch marks, which cannot be removed. Never allow any liquid cleaning materials to dry on the glass surfaces as this will leave water marks which will be very difficult to remove. Use only mild detergents.

Regular cleaning with Wardray's professional strength Glass Cleaner will ensure surfaces remain clean and clear of any surface grease.

We also make the following recommendations:

- ▶ **General cleaning for the removal of dust film etc. -**
Use a soft cotton cloth together with isopropyl alcohol and clean in a smooth circular motion
- ▶ **Cleaning of difficult stains -**
Use a mild detergent diluted with water to the manufacturer's recommendations and clean with a soft cotton cloth. Using a further soft cotton cloth clean with isopropyl alcohol



Regular cleaning with Wardray's professional strength Glass Cleaner will ensure surfaces remain clean and clear of any surface grease



QUALITY WITHOUT COMPROMISE
FROM THE UK'S LEADING
RADIATION SHIELDING

WARDRAY PREMISE LTD

Hampton Court Estate
Summer Road
Thames Ditton
Surrey KT7 0SP
Tel: +44 (0) 20 8398 9911
Fax: : +44 (0) 20 8398 8032
E-mail: sales@wardray-premise.com

Full details of all products and services can be viewed on our website:

www.wardray-premise.com

SUCCESSFULLY TRADING
FOR 100 YEARS

GEN.S.12.226